

REPORT of SURVEY for REPAIRS.

23133

No. ³⁷ on the *"Bark Indiana"* Survey held at *London* Date *20th April* 18*60*

Tonnage *542* ~~593~~ Built at *Montrose* When built *1852*

By whom built _____ Owners *Madams*

Port belonging to *Montrose* Destined Voyage *Newcastle & India*

If Surveyed Afloat or in Dry Dock *Ratcliff Cross dock*

Last Survey, No. *21386* Port *London* Classed *12 A 1*

REPAIRS

at present bottom stripped Caulked and sheathed with Yellow Metal on fitt -

Present Condition of the

Decks <i>Good</i>	Treenails _____	Windlass and Capstan <i>Good</i>
Waterways <i>to be Caulked</i>	Breasthooks and Stemson _____	Pumps _____
Comings <i>Good</i>	Transoms, Pointers, and Crutches _____	Boats <i>four</i>
Upper Deck Beams & Fastenings <i>do</i>	Timbers of the Frame _____	Masts, Yards, &c. <i>Sufficient</i>
Lower Deck Beams & Fastenings <i>do</i>	Keelsons _____	Sails _____
Planksheers } <i>Good</i>	Clamps and Shelves _____	Anchors No. of <i>3 1 1</i>
Sheerstrakes } <i>Good</i>	Ceiling _____	Cables <i>Sufficient</i>
Topsides } <i>Good</i>	Rudder <i>Main piece broken</i>	Hawsers and Warps <i>do</i>
Wales } <i>Good</i>	Copper <i>Ym</i> When put on <i>April 1860</i>	Standing & Running Rigging <i>do</i>
Plank (Bottom) and Counter <i>good</i>	Caulking of Bottom, Deck, & Waterways. <i>tests good</i>	

General Observations and Opinion,

This Vessel is now in good & efficient Condition & fit to remain at Class

The Amount of Fee.....£ : : is received by me,

J. H. Ritchie

Special..... : :

Certificate (if required) : :

Committee's Minute *8th May* 18*60*

Character assigned *12 A 1*



© 2019

Lloyd's Register Foundation

LON 642-0348