

ANNUAL SURVEYS.

23251

No. 829 on the B-1 Susan Bayley Survey held at London Date June 15 1860
 Master J. Daniel
 Tonnage 158 Built at Ipswich When built 1853
 By whom built Bayley Owners Bayley & Co.
 Port belonging to Ipswich Destined Voyage Mountain Dock Ways
 If Surveyed Afloat or in Dry Dock Ipswich

Last Survey, No. 980 Port of Ipswich Classed 13 A 1
59

The present Condition of the
 Decks good Treenails seen Windlass and Capstan good
 Waterways 1 Breasthooks and Stemson seen Pumps 1
 Comings 1 Transoms, Pointers, and Crutches seen Boats good & sufficient
 Upper Deck Beams & Fastenings good Timbers of the Frame good Masts, Yards, &c. 1
 Lower Deck Beams & Fastenings where Keelsons where Sails 1
 Planksheers seen Clamps and Shelves seen Anchors No. of 1
 Sheerstrakes 1 Ceiling 1 Cables 1
 Topsides 1 Rudder 1 Hawser and Warps 1
 Wales 1 Copper Y.M. When put on 1859 Standing & Running Rigging 1
 Plank (Bottom) and Counter 1 Caulking of Bottom, Deck, and Waterways good where seen

General Observations and Opinion,
Now done. 5 broken rafter on the Starboard side renewed
also the rail in way of the same, upper works painted in
way of new work. - She now appears in good condition
and in my opinion eligible to remain as Classed 13 A 1.
 Committee's Minute 6th July 1860
 Character assigned 13 A 1 J. F. R. Light
 Certificate (if required)

No. 593 on the Ship Mary Scott Survey held at London Date June 23 1860
 Master R. Thompson
 Tonnage 588 Built at London When built 1859
 By whom built Booth Owners Scott & Co.
 Port belonging to London Destined Voyage Brodie's Dry Dock
 If Surveyed Afloat or in Dry Dock Brodie's Dry Dock

Last Survey, No. 5593 Port of London Classed 10 A 1
59

The present Condition of the
 Decks good Treenails seen Windlass and Capstan good
 Waterways 1 Breasthooks and Stemson seen Pumps 1
 Comings 1 Transoms, Pointers, and Crutches seen Boats good & sufficient
 Upper Deck Beams & Fastenings good Timbers of the Frame good Masts, Yards, &c. 1
 Lower Deck Beams & Fastenings where Keelsons where Sails 1
 Planksheers 1 Clamps and Shelves seen Anchors No. of 1
 Sheerstrakes 1 Ceiling 1 Cables 1
 Topsides 1 Rudder 1 Hawser and Warps 1
 Wales 1 Copper Y.M. When put on now done Standing & Running Rigging 1
 Plank (Bottom) and Counter 1 Caulking of Bottom, Deck, and Waterways good where tested

General Observations and Opinion,
Now done. yellow metal stripped, butts of bottom and
good end chalked, and yellow metal renewed on felt. - She
is now in good condition, and in my opinion eligible to remain
as Classed 10 A 1.
 Committee's Minute 6th July 1860
 Character assigned 10 A 1 J. F. R. Light
 Certificate (if required)