

REPORT of SURVEY for REPAIRS.

23271

No. 365 on the S. "Holmsdale" Survey held at London Date 11th to 14th June 1860
 Master W. Dennis
 Tonnage 1257 Built at Sunderland When built 1858
 By whom built _____ Owners Phillipps
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Rep^y Green's dry dock

Last Survey, No. 21753 Port London Classed B 21
 88

REPAIRS

Yellow metal stripped off recaulked from keel to upper part of wales and resheathed with Yellow metal on paper new Caulking tested and found satisfactory

Present Condition of the

Decks	} <u>good</u>	Treenails	} <u>good</u>	Windlass and Capstan	} <u>in good</u>
Waterways		Breasthooks and Stems		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Keelsons	} <u>where</u>	Sails	} <u>order and</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales	} <u>seen</u>	Copper <u>Y^l Mo^r paper</u> When put on <u>June 1860</u>	} <u>supp</u>	Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

good where tested
 This Ship is at present in good condition and in our opinion eligible to continue as Classed B 21

The Amount of Fee.....£ _____ is received by me,

Special atten- } 1 : 1 : -
 dance & caulked }
 Certificate (if required) _____

Committee's Minute 13th July 1860

Character assigned B 21

record M^r W. C. H.



© 2019

Lloyd's Register Foundation

LON643-0042