

No.

Survey held at

London

Date

July 5th

1860

23286

on the

Ship "Vanguard"

Master

Arthur Scott

Tonnage

626

Built at

Sunderland

When built

1837

By whom built

Owners

S. Pelsor

Port belonging to

Shields

Destined Voyage

If Surveyed Afloat or in Dry Dock

Limekiln Dry Dock -

Last Survey, No.

22565

Port of

London

Classed

13 A 1.

59

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Treenails

Breasthooks and Stenson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

Yellow Paint

Copper on Selt

When put on

1839

Caulking of Bottom, Deck, and Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Good where seen

Committee's Minute

17th July

1860

Character assigned

13 A 1

Certificate (if required).

Lloyd's Register
Foundation

LON643-0056