

REPORT of SURVEY for REPAIRS.

No. 6 Survey held at London Date 13th to 17th Oct^r 1859
 on the S. "Kent" Master Clayton
 Tonnage 879 Built at London When built 1833
 By whom built 998 Owners Wijmans'
 Port belonging to London Destined Voyage _____

If Surveyed Afloat or in Dry Dock Wijmans' dry dock

Last Survey, No. 22260 Port London Classed 13 A1

REPAIRS

Sellow Metal stripped off scautree from keel to
metal line and remetalled on feet
new caulking tested and found good

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>Oct 1859</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

She is now in good condition and eligible to
continue as classed 13 A1

The Amount of Fee.....£ : : is received by me,

Special auth^r 1:1:1

Certificate (if required) : :

Committee's Minute 10th August 1860

Character assigned 13 A1

record 9M



© 2019

Lloyd's Register
Foundation

LCN 643-0118