

ANNUAL SURVEYS.

23422

No. ¹³⁸ on the *B^c "Caroline"* Survey held at *London* Date *1st Sep 12* 18 *60*
 Tonnage *341* Built at *London* When built *1841*
 By whom built *426* Owners *Cottam &*
 Port belonging to *London* Destined Voyage _____
 If Surveyed Afloat or in Dry Dock *Nelson dry dock*

West 19. 100

Last Survey, No. *21482* Port of *London*

Classed *12 A1*
Rest 2 57-78 44

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales <i>double on feet</i>	Copper <i>1 1/2</i>	Standing & Running Rigging
Plank (Bottom) and Counter <i>part double</i>	When put on <i>1857</i>	

General Observations and Opinion, *Caulking of Bottom, Deck, and Waterways* *Good where seen*
Tell me metal patches where required. she appears
at present in good condition and eligible in my opinion to
continue as classed A1

Will: C. P. Davey

Committee's Minute *18th September 1860.*

Character assigned

Certificate (if required)

No. ³⁷⁸ on the *S. "Sevilla"* Survey held at *London* Date *4th Sep 12* 18 *60*
 Tonnage *598* Built at *Jersey* When built *1859*
 By whom built *Clarke* Owners *Turnbull &*
 Port belonging to *Glasgow* Destined Voyage _____
 If Surveyed Afloat or in Dry Dock *Nelson dry dock*

Last Survey, No. *966* Port of *Jersey*

Classed *12 A1*
59

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <i>sem</i>	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings <i>Beams</i>	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <i>1 1/2</i>	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <i>1859</i>	

General Observations and Opinion, *Caulking of Bottom, Deck, and Waterways* *Good where seen*
locked to right bottom she appears sound and
firm and eligible in my opinion to continue as classed 12 A1

Will: C. P. Davey

Committee's Minute *18th September 1860.*

Character assigned

Certificate (if required).

Lloyd's Register
 Foundation

LOW 043-0185