

ANNUAL SURVEYS.

23478
Rev 8/10/60

No. 23 Survey held at London Date 13th April 1860
 on the S. "General Reill" Master Black
 Tonnage 970 Built at Quebec When built 1858
 By whom built _____ Owners S. St Watt
 Port belonging to Glasgow Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Mr Green's dry dock

Last Survey, No. 358 Port of Quebec Classed 7A1

The present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	} <u>In good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Keelsons	} <u>where</u>	Sails	} <u>order and</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales	} <u>seen</u>	Copper <u>8 1/2 in</u> When put on <u>1859</u>	} <u>suffr</u>	Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion, CaULKING of Bottom, Deck, and Waterways Good where seen
locked to sight bottom. This ship is at present in good condition and
in my opinion eligible to continue as classed 7A1

Willm B Davey

Committee's Minute 9th October 1860
 Character assigned 7A1 WMB

Certificate (if required)

No. 450 Survey held at London Date 21st Decr 1860
 on the S. "Alnwick Castle" Master Right
 Tonnage 1087 Built at Sunderland When built 1856
 By whom built _____ Owners R Green
 Port belonging to London Destined Voyage East Indies
 If Surveyed Afloat or in Dry Dock Mr Green's dry dock

Last Survey, No. 21189 Port of London Classed 13A1

The present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	} <u>In good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Keelsons	} <u>where</u>	Sails	} <u>order and</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales	} <u>seen</u>	Copper <u>1 in</u> When put on <u>1857</u>	} <u>suffr</u>	Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion, CaULKING of Bottom, Deck, and Waterways Good where seen
locked to sight bottom. she appears in good condi-
tion and eligible in our opinion to continue as classed 13A1

Willm B Davey

Committee's Minute 9th October 1860
 Character assigned 13A1 WMB

Certificate (if required).

