

# ANNUAL SURVEYS.

23526

Recd 1/11/60

No. <sup>308</sup> Survey held at London Date Oct 19<sup>th</sup> 18 60  
 on the Barge "William & Jane" Master R. Morris  
 Tonnage 459 Built at Sunderland When built 1833  
 By whom built 450 Owners Ships Stuart &  
 Port belonging to London Destined Voyage Singapore  
 If Surveyed Afloat or in Dry Dock Lincolns Dock Ship

Last Survey, No. 22645 Port of London Classified S.A. 1.  
 59

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good where</u>	Breasthooks and Stemson	Pumps
Comings } <u>seen</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame } <u>Good where</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <u>firm</u>	Keelsons } <u>seen</u>	Sails
Planksheers	Clamps and Shelves	Anchors No. of } <u>Sufficient</u>
Sheerstrakes } <u>Caulked</u>	Ceiling	Cables
Topsides	Rudder } <u>Yellow Metal</u>	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>1839</u>	

General Observations and Opinion: Caulking of Bottom, Deck, and Waterways Good where seen  
Now done, the upper part of the and brace of the Rudder renewed, the deck house dispensed with and her sides Caulked from the Yellow Metal sheathing to the waterway seam - She is now fit in my opinion to remain as classed S.A. 1.

Committee's Minute 2nd November 1860  
 Character assigned S.A. 1

B. Weymouth

Certificate (if required)

No. <sup>218</sup> Survey held at London Date Oct 30<sup>th</sup> 18 60  
 on the Ship "Aladdin" Master Wood  
 Tonnage 867 Built at Maryport When built 1834  
 By whom built Owners J. St. Rini  
 Port belonging to Liverpool Destined Voyage  
 If Surveyed Afloat or in Dry Dock Union Dry Dock Co.

Last Survey, No. 15572 Port of Liverpool Classified 13.A. 1.  
 59

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good where</u>	Breasthooks and Stemson	Pumps
Comings } <u>seen</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame } <u>Good where</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <u>firm</u>	Keelsons } <u>seen</u>	Sails
Planksheers	Clamps and Shelves	Anchors No. of } <u>Sufft</u>
Sheerstrakes } <u>Caulked</u>	Ceiling	Cables
Topsides	Rudder } <u>Yellow Metal</u>	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>1839</u>	

General Observations and Opinion: Caulking of Bottom, Deck, and Waterways Good where seen  
Now done, her sides Caulked from the Metal sheathing to the Gunwale - She is now fit in my opinion to remain as classed 13.A. 1.

Committee's Minute 2nd November 1860  
 Character assigned 13.A. 1

B. Weymouth

Certificate (if required).

© 2019 Lloyd's Register Foundation

LON 643 - 0276