

ANNUAL SURVEYS.

23574

No. 308 Survey held at London Date Oct 15th 1860
on the Barque "Indubious" Master Foster
Tonnage 550 Built at Sunder When built 1848
By whom built 601 Owners P. Mann
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Sup^{ts} Youngs Dry Dock

Last Survey, No. 22628 Port of London Classed 12 A. 1.
59

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	<u>Yellow Metal</u>	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on <u>1839</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done, she has been scraped bright from the metal sheathing to the gunwale, but the Owner declined having her surveyed for continuation as it is his intention to sell her in her present condition.

Committee's Minute 27th November 1860

Character assigned Deferred

P. Weymouth

Certificate (if required)

No. 34 Survey held at London Date Oct 22nd 1860
on the Ship "Hannover" Master Rich
Tonnage 1045 Built at Shields When built 1833
By whom built _____ Owners G. Marshall
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Sup^{ts} Youngs Dry Dock

Last Survey, No. 22657 Port of London Classed 13 A. 1.
59

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good where seen</u>	Breasthooks and Stemson	Pumps
Comings } <u>seen</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. } <u>Good and</u>
Lower Deck Beams & Fastenings } <u>firm</u>	Keelsons	Sails } <u>suff^{ts}</u>
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes } <u>Good where seen</u>	Ceiling	Cables
Topsides } <u>Good where seen</u>	Rudder	Hawsers and Warps
Wales	<u>Yellow Metal</u>	Standing & Running Rigging
Plank (Bottom) and Counter	Copper on <u>Felt</u> When put on <u>now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done, the yellow metal sheathing has been renewed, but not the felt. She is in good condition fit in my opinion to remain as classed 13 A. 1.

Committee's Minute 27th November 1860

Character assigned 13 A. 1

record 9M

P. Weymouth

Certificate (if required).