

# ANNUAL SURVEYS.

23575

No. 300 on the Ship "Galconda" Survey held at London Date Nov 7<sup>th</sup> 1860  
 Tonnage 688 Built at Sunderland Master E. Montgomerie  
 By whom built Owners G. Wade  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock Inps Carters Dry Dock

Dec 24. 11.60

Last Survey, No. 22535 Port of London Classed 10<sup>th</sup> 1.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } Good	Breasthooks and Stemson	Pumps } Good & Suff
Comings }	Transoms, Pointers, and Crutches	Boats }
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. New Ruzin Mast
Lower Deck Beams & Fastenings } firm	Keelsons } Good where	Sails
Planksheers	Clamps and Shelves } seen	Anchors No. of }
Sheerstrakes } Good where seen	Ceiling	Cables } Good and
Topsides }	Rudder } Metal	Hawsers and Warps } suff.
Wales }	Copper on felt When put on New	Standing & Running Rigging
Plank (Bottom) and Counter Caulked		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done, she has been caulked from the keel to the metal sheathing line, her bottom resheathed with yellow metal on felt - she is now fit in my opinion to remain as classed 10<sup>th</sup> 1.

Committee's Minute 27<sup>th</sup> November 1860

Character assigned

10<sup>th</sup> 1

B. Weymouth

Charge £ 1. 1. 0

Certificate (if required)

No. 332 on the Barque "Poitiers" Survey held at London Date Nov 8<sup>th</sup> 1860  
 Tonnage 404 Built at Sunderland Master Howard  
 By whom built Owners J. Dunbar  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock Inps Carters Dry Dock

Last Survey, No. 22641 Port of London

Classed Red A. 1. 2<sup>nd</sup> Clause.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } Good where	Breasthooks and Stemson	Pumps }
Comings }	Transoms, Pointers, and Crutches	Boats }
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. }
Lower Deck Beams & Fastenings } Good	Keelsons } Good where	Sails } Good and
Planksheers	Clamps and Shelves } seen	Anchors No. of }
Sheerstrakes } Good where	Ceiling	Cables }
Topsides }	Rudder } Metal	Hawsers and Warps }
Wales }	Copper on felt When put on 1859	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done, her metal sheathing patched and the after wood ends caulked - she is now fit in my opinion for the safe conveyance of dry and perishable cargoes to and from all parts of the world

Committee's Minute 27<sup>th</sup> November 1860

Character assigned

A 1 in Red

S. S. 56 - 6 Years

B. Weymouth

Certificate (if required).

Lloyd's Register Foundation  
 LON 643-0321