23597

ANNUAL SURVEYS.

No. 317 Survey held at London Date Sep 26th 1860
on the Barque "Duke of Roxburg" Master
Tonnage 417 Built at Newcastle When built 1828
By whom built Owners Messrs Crozier &
Port belonging to London Destined Voyage
If Surveyed Afloat or in Dry Dock Messrs Youngs Dry Dock -

Rec 6.12.60 Ent

Last Survey, No. 22390 Port of London Classed Red A 1.
Rest 46-8½ ns C. 3 59

The present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	Good where seen	Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	firm	Timbers of the Frame	Good where seen	Masts, Yards, &c.	Good and suff^t
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelfs		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides	Good where seen	Rudder		Hawsers and Warps	
Wales		Yellow Metal ~~Copper~~	When put on	Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where seen

Now done, her Metal Sheathing Patched - She is now fit in my opinion for the safe Conveyance of dry and perishable Cargoes to and from all Parts of the World and to remain Classed Red A 1.

Committee's Minute 7th December 1860. B. Waymouth

Character assigned

deferred

Certificate (if required)

No. 216 Survey held at London Date Oct 11th 1860
on the Barque "Alacrity" Master Cooper
Tonnage 317 Built at Sunderland When built 1834
By whom built Owners J. Todd
Port belonging to London Destined Voyage Cape of Good Hope
If Surveyed Afloat or in Dry Dock Clyde Dry Dock & London Dock -

Last Survey, No. 21941 Port of London Classed 8 A 1.
58

The present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	Good where seen	Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	firm	Timbers of the Frame	Good where seen	Masts, Yards, &c.	Good and suff^t
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelfs		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides	Caulked	Rudder		Hawsers and Warps	
Wales		Y Metal ~~Copper~~ on Felt	When put on Now	Standing & Running Rigging	
Plank (Bottom) and Counter	Caulked				

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where tested

Now done the Yellow Metal Sheathing renewed on Felt, She has been Caulked from Keel to the Gunwale, and a Plank each side in the deck, next the waterway renewed - She is now fit in my opinion to remain as classed 8 A 1.

Committee's Minute 7th December 1860

Character assigned 8 A 1

Charge £1.1.0 record

B. Waymouth

Certificate (if required).

© 2019 Lloyd's Register Foundation

LON643-0343