

# ANNUAL SURVEYS.

No. 538 Survey held at London Date Nov 30 Dec 15 1860  
on the Ship Jubilee Master A Jones  
Tonnage 764 Built at Washington When built 1857  
By whom built London Owners Mr Brodie & Co  
Port belonging to London Destined Voyage China  
If Surveyed Afloat or in Dry Dock In Mr Benson's Dock by Day & Night & Afloat in N India Dock

Last Survey, No. 22808 Port of London Classed 14 A 1  
59

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stemson } <u>good where seen</u>	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>all appear in good condition</u>
Lower Deck Beams & Fastenings <u>where seen</u>	Keelsons <u>bt seen where</u> <u>dit</u>	Sails <u>where seen</u>
Planksheers	Clamps and Shelves <u>dit</u>	Anchors No. of <u>3 B, 1 S, 2 K</u>
Sheerstrakes <u>dit</u>	Ceiling <u>dit</u>	Cables
Topsides <u>dit</u>	Rudder <u>dit</u>	Hawsers and Warps
Wales <u>dit</u>	Copper <u>dit</u> When put on <u>59 dit</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>dit</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

Now done. Dock'd to examine Bottom; She appeared to be in good condition, eligible to remain as Classed A 1

Committee's Minute 21<sup>st</sup> December 1860

Character assigned 14 A 1

Certificate (if required)

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
on the \_\_\_\_\_ Master \_\_\_\_\_  
Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18\_\_\_\_

Character assigned \_\_\_\_\_

Certificate (if required).



© 2019

Lloyd's Register Foundation

LDN 643-0373