

# ANNUAL SURVEYS.

23752

No. 146 on the S. "Orient" Survey held at London Date 23<sup>rd</sup> Feb 4<sup>th</sup> Mar 1861  
 Tonnage 1133 Built at London Master Lawrence  
 By whom built 1032 Owners Thomson &  
 Port belonging to London Destined Voyage Adelaide  
 If Surveyed Afloat or in Dry Dock Nelson dry dock & London dock

Last Survey, No. 23200 Port of London Classed S A 1  
 60

The present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	<u>2 No do</u>
Comings		Transoms, Pointers, and Crutches		Boats	<u>4 No do</u>
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	<u>new True 92 do</u>
Lower Deck Beams & Fastenings	} <u>where</u>	Keelsons	} <u>where</u>	Sails	<u>2 suits do</u>
Planksheers		Clamps and Shelves		Anchors No. of	<u>3 B. 15 &amp; 14 do</u>
Sheerstrakes		Ceiling		Cables	<u>do</u>
Topsides		Rudder		Hawsers and Warps	<u>3 No do</u>
Wales	} <u>seen</u>	Copper <u>Thom</u> When put on	} <u>seen</u>	Standing & Running Rigging	<u>do</u>
Plank (Bottom) and Counter		<u>1860</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where tested  
Docked to sight bottom. 4 upper seams of outside  
planking recaulked also waterways and 4 seams of deck rest the  
waterways. she appears where seen in good condition and eligible  
in our opinion to continue as classed A1 Will <sup>m</sup> C. Davey  
 J. S. Martin

Committee's Minute 8<sup>th</sup> March 1861

Character assigned S A 1 W

Certificate (if required)

No. 385 on the S. "Wynand" Survey held at London Date 26<sup>th</sup> Feb 4 1861  
 Tonnage 596 Built at London Master Reid  
 By whom built 546 Owners A. G. Robinson  
 Port belonging to London Destined Voyage Shanghai  
 If Surveyed Afloat or in Dry Dock Nelson dry dock

Last Survey, No. 23002 Port of London Classed 13 A 1  
 60

The present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	} <u>In good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Keelsons	} <u>where</u>	Sails	} <u>order &amp;</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales	} <u>seen</u>	Copper <u>Wyn</u> When put on	} <u>seen</u>	Standing & Running Rigging	<u>do</u>
Plank (Bottom) and Counter		<u>1860</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen  
Docked to sight bottom. one piece of false keel  
removed she appears where seen in good condition and in our  
opinion eligible to continue as classed A1 Will <sup>m</sup> C. Davey  
 J. S. Martin

Committee's Minute 8<sup>th</sup> March 1861

Character assigned 13 A 1 W

Certificate (if required).