

23883

REPORT of SURVEY for REPAIRS.

No. 16 Survey held at London Date 3rd 6th 12th April 1861
 on the Bk Lady Alice Master Smith
 Tonnage 120 Built at Sunderland When built 1858
 By whom built _____ Owners Wilkinson
 Port belonging to London Destined Voyage Lon. Toulon & China
 If Surveyed Afloat or in Dry Dock St. Mathias Docks

Last Survey, No. 21035 Port London Classed 10A1
5A.

REPAIRS

This Vessel had five pairs of knee riders and two pairs of main riders fitted to her last year, and was also re-stayed on felt at Lisbon in March 1860.

A large pair of iron knees have now been added crossing the stern and quarter timbers, the whole of the ceiling redgeed and refastened, and the plank sheers additionally bolted.

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>Sufficient</u>
Plank sheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>Good where seen</u>	Ceiling <u>"</u>	Cables <u>where</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>on felt</u> When put on <u>3. 60.</u>	Standing & Running Rigging <u>seen</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen

This Vessel is in good and efficient condition eligible to remain as classed 10A1

The Amount of Fee £ 1 : — : — is received by me,

Special Attchd. 1 : 1 : —

Certificate (if required) : 5 : —

Committee's Minute 23rd April 1861

Character assigned 10A1

Record repair



© 2021

Lloyd's Register
Foundation

LONG44-0145