

ANNUAL SURVEYS.

23912

No. 152 on the

Survey held at

London

Date

Apr. 9th & May 2nd 1861

Ship

Vile

Master

Mr. F. J. Owen

Tonnage

1100

Built at

London

When built

1850

By whom built

London

Owners

St. Green

Port belonging to

London

Destined Voyage

If Surveyed Afloat or in Dry Dock

Messrs Green's Dry Dock and Co. J. Dock

Last Survey, No. 21708

Port of

London

Classed

12 A1

The present Condition of the

Decks partly Caulked
Waterways "
Comings good
Upper Deck Beams & Fastenings good
Lower Deck Beams & Fastenings where seen
Planksheers "
Sheerstrakes Butts Caulked
Topsides "
Wales "
Plank (Bottom) and Counter Caulked

Treenails
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame good
Keelsons where seen
Clamps and Shelves seen
Ceiling
Rudder
Copper Y.M. When put on now done

Windlass and Capstan good
Pumps "
Boats good & sufficient
Masts, Yards, &c. new fore-mast
Sails "
Anchors No. of "
Cables "
Hawsers and Warps "

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Standing & Running Rigging good where seen

Committee's Minute

Now done, yellow metal stripped, except in the upper courses and bottom. Caulked in way of the same. Decks partly Caulked, also the butts of upper works, new fore steps, hung in stores, and yellow metal renewed on fore side. She is now in good condition and in my opinion eligible to remain as Classed A1.

Character assigned

12 A1

Certificate (if required)

Charge for testing Caulking £1.1.3

No. 1293 on the

Survey held at

London

Date

Apr. 25th & May 18th 1861

Ship

St. Lawrence

Master

C. Light

Tonnage

1293

Built at

London

When built

1860

By whom built

London

Owners

Green

Port belonging to

London

Destined Voyage

If Surveyed Afloat or in Dry Dock

Green's Dry Dock and Co. J. Dock

Last Survey, No. 23260

Port of

London

Classed

13 A1

The present Condition of the

Decks Caulked
Waterways "
Comings good
Upper Deck Beams & Fastenings very good
Lower Deck Beams & Fastenings where seen
Planksheers good
Sheerstrakes Caulked
Topsides "
Wales "
Plank (Bottom) and Counter good where seen

Treenails
Breasthooks and Stemson
Transoms, Pointers, and Crutches good
Timbers of the Frame where seen
Keelsons seen
Clamps and Shelves
Ceiling
Rudder
Copper Y.M. When put on "

Windlass and Capstan good
Pumps "
Boats good & sufficient
Masts, Yards, &c. "
Sails "
Anchors No. of "
Cables "
Hawsers and Warps "

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Standing & Running Rigging good where seen

Committee's Minute

Now done, yellow metal patched, Caulked from metal upward and deck. She is now in good condition and in my opinion eligible to remain as Classed 13 A1.

Character assigned

13 A1

Certificate (if required)

LON644-0173

