

23920

REPORT of SURVEY for REPAIRS.

No. 26 Survey held at London Date 12th 2nd Feb 1861
on the B^k F. Aling Grove Master _____
Tonnage 324 Built at Redbridge When built 1841
By whom built _____ Owners Brodie
Port belonging to London Destined Voyage Am
If Surveyed Afloat or in Dry Dock Princes Dock & W. J. Deeks

Last Survey, No. 23759 Port London Classed 13B1
REPAIRS Verb 37. 9 - 39

The yellow metal sheathing stripped the bottom caulked and resheathed with Gm on felt.

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good where seen</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Boats	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Good where seen</u>	Timbers of the Frame	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>Seen</u>	Keelsons	<u>"</u>	Sails	<u>Sufficient</u>
Planksheers	<u>"</u>	Clamps and Shelves	<u>"</u>	Anchors No. of	<u>"</u>
Sheerstrakes	<u>"</u>	Ceiling	<u>"</u>	Cables	<u>Where</u>
Topsides	<u>"</u>	Rudder	<u>"</u>	Hawsers and Warps	<u>"</u>
Wales	<u>"</u>	Copper	<u>Gm on Felt When put on Now stone</u>	Standing & Running Rigging	<u>Seen</u>
Plank (Bottom) and Counter	<u>"</u>				

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tried

This Vessel is in good and efficient condition, eligible to remain as classed A

The Amount of Fee.....£ : : is received by me,

Special Survey... 1 : 1 : -
Certificate (if required) 2 : 2 : -

Committee's Minute 11th May 1861

Character assigned Rest 9th 1st second Gm.



© 2021

Lloyd's Register
Foundation

L ON 644 - 0180