

ANNUAL SURVEYS.

24027

Recd 8/7/61

No. 339 Survey held at London Date May to June 27th 1861
 on the Ship "Windward" Master Lulham
 Tonnage 620 Built at Sunderland When built 1860
 By whom built _____ Owners Senwick
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Union Dry Dock & London Dock

Last Survey, No. 23969 Port of London Classed 13A.1.
 5.61

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stenson	Pumps
Comings }	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. } <u>Good and</u>
Lower Deck Beams & Fastenings } <u>Good</u>	Keelsons } <u>Good where</u>	Sails } <u>suff.</u>
Planksheers	Clamps and Shelves } <u>seen</u>	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides } <u>Good</u>	Rudder	Hawsers and Warps
Wales	Yellow Metal	Standing & Running Rigging
Plank (Bottom) and Counter <u>Caulked</u>	Copper on felt } When put on <u>now</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where tested
Now done the yellow metal sheathing renewed on felt - she has been hung in place and caulked from the keel to the metal line and is now fit in my opinion to remain classed 13A.1.

Committee's Minute 5th July 1861

Character assigned 13A.1 second class

Charge £ 1. 1. 0

Certificate (if required)

No. 886 Survey held at London Date May to June 27th 1861
 on the Ship "Antipodes" Master Croft
 Tonnage 592 Built at Sunderland When built 1833
 By whom built _____ Owners M^{rs} P. Person

Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Imp^{rs} Sutchers Dry Dock & London Dock

Last Survey, No. 23344 Port of London Classed 13A.1
 60

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good where</u>	Breasthooks and Stenson	Pumps
Comings } <u>seen</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame } <u>Good where</u>	Masts, Yards, &c. } <u>Good and</u>
Lower Deck Beams & Fastenings } <u>firm</u>	Keelsons } <u>seen</u>	Sails } <u>suff.</u>
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides } <u>Good where</u>	Rudder	Hawsers and Warps
Wales } <u>seen</u>	Copper	Standing & Running Rigging
Plank (Bottom) and Counter <u>Good</u>	When put on	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where seen
She is in good and efficient Condition. fit in my opinion to remain as classed 13A.1.

Committee's Minute 5th July 1861

Character assigned 13A.1

© 2021
 Lloyd's Register
 Foundation

LON644-0281