

REPORT of SURVEY for REPAIRS.*Change of Owner*

Rev 17/1/61

No. 231 Survey held at London Date 13th July 1861
 on the Ship "Queen Glendores" Master J. Robinson
 Tonnage 455 Built at London When built 1839
 By whom built _____ Owners John Hay
 Port belonging to London Destined Voyage for India
 If Surveyed Afloat or in Dry Dock East India Dock

Last Survey, No. 23490 Port London Classed 2A1
 Repairs Rest. D.

The ceiling in the hold piece and repaired and the frame where exposed found good. A new whistle of 20 fitted in lieu of riding bit.

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps <u>Good</u>
Comings <u>Good</u>	Transoms, Pointers, and Crutches <u>Good</u>	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Efficient</u>	Keelsons <u>Efficient</u>	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of <u>Sufficient</u>
Sheerstrakes _____	Ceiling <u>Where seen</u>	Cables _____
Topsides <u>Where</u>	Rudder <u>Where seen</u>	Hawsers and Warps <u>Where</u>
Wales _____	Copper <u>When put on 1850</u>	Standing & Running Rigging <u>Seen</u>
Plank (Bottom) and Counter <u>Seen</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen

This ship appears to be in good and efficient condition eligible to remain as classed A1

The Amount of Fee.....£ 1 : - : is received by me,

Special..... : - : H

Certificate (if required) : 5 : -

Gen Committee's Minute 18th July 1861Character assigned Cont.° Rest.° 8 A1

© 2021

Lloyd's Register
Foundation

LON644-0300