

ANNUAL SURVEYS. 24054

No. ¹⁸ on the *Ship "York"* Survey held at *London* Date *19th July* 18*61*
 Tonnage *65* Built at *Sunderland* Master *Reaper*
 By whom built *John* Owners *John*
 Port belonging to *London* Destined Voyage *See*
 If Surveyed Afloat or in Dry Dock *Wigams dry dock*

Last Survey, No. *22637* Port of *London* Classed *13A1*
59

The present Condition of the

Decks <i>Good</i>	Treenails <i>Good</i>	Windlass and Capstan <i>Good</i>
Waterways	Breasthooks and Stemson	Pumps
Comings <i>Good</i>	Transoms, Pointers, and Crutches <i>Good</i>	Boats <i>Good</i>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings <i>Efficient</i>	Keelsons <i>Efficient</i>	Sails <i>Sufficient</i>
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes <i>Where</i>	Ceiling <i>Where</i>	Cables <i>Where</i>
Topsides	Rudder <i>Seen</i>	Hawsers and Warps
Wales	Copper <i>Seen</i> When put on <i>1859</i>	Standing & Running Rigging <i>Seen</i>
Plank (Bottom) and Counter <i>Seen</i>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways *Good where seen*

This vessel is in good and efficient condition, eligible to remain as classed 13A1.

Committee's Minute *19th July* 18*61*

Character assigned *13A1*

Certificate (if required)

No. ⁵⁴ on the *Ship "Barham"* Survey held at *London* Date *9th July* 18*61*
 Tonnage *1119* Built at *London* Master *Cousins*
 By whom built *John* Owners *R. Green*
 Port belonging to *London* Destined Voyage *See India*
 If Surveyed Afloat or in Dry Dock *Green's dry dock*

Last Survey, No. *23701* Port of *London* Classed *12A1*
Can 50. 4. 60

The present Condition of the

Decks <i>Good</i>	Treenails <i>Good</i>	Windlass and Capstan <i>Good</i>
Waterways	Breasthooks and Stemson	Pumps
Comings <i>Good</i>	Transoms, Pointers, and Crutches <i>Good</i>	Boats <i>Good</i>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings <i>Efficient</i>	Keelsons <i>Efficient</i>	Sails <i>Sufficient</i>
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes <i>Where</i>	Ceiling <i>Where</i>	Cables <i>Where</i>
Topsides	Rudder <i>Seen</i>	Hawsers and Warps
Wales	Copper <i>Seen</i> When put on <i>1860</i>	Standing & Running Rigging <i>Seen</i>
Plank (Bottom) and Counter <i>Seen</i>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways *Good where seen*

This vessel is in good and efficient condition, eligible to remain as classed 12A1.

Committee's Minute *19th July* 18*61*

Character assigned *Can 4A1*

Certificate (if required).



Lloyd's Register Foundation

LON644-0305