

# REPORT of SURVEY for REPAIRS.

No. 874 on the S<sup>c</sup> Swallow Survey held at London Date June 20<sup>th</sup> 18 67  
 Tonnage 149 Built at Gosport Master Collings When built 1856  
 By whom built \_\_\_\_\_ Owners Camper & Collings & Co.  
 Port belonging to Portsmouth Destined Voyage See Note annexed  
 If Surveyed Afloat or in Dry Dock \* London Fountain dry dock \* See Note annexed

Last Survey, No. 21407 Port London Classed 13 A 1

## REPAIRS

*Yellow metal stripped caulked from keel to metal line and yellow metal renewed upon paper*

### Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>T.M.</u> When put on <u>now</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

### General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

*This vessel is now in good condition and is eligible in my opinion to remain classed*  
13 A 1

The Amount of Fee.....£ 10 : is received by me,

Special..... 1 : 1 :

Certificate (if required) \_\_\_\_\_

Committee's Minute 6<sup>th</sup> August 18 67

Character assigned 13 A 1



© 2021

Lloyd's Register  
Foundation

LON644-0333