

ANNUAL SURVEYS.

24088

No. 172 Survey held at London Date July 9th 10th 18 61
 on the Brig "Agnes" Master J. Ferris
 Tonnage 177 Built at Barnstable When built 1838
 By whom built W. Sparke Owners W. Sparke
 Port belonging to London Destined Voyage Princes' Day Dock
 If Surveyed Afloat or in Dry Dock Princes' Day Dock

Last Survey, No. 22890 Port of London Classed 13 A 1
 1.60

The present Condition of the

Decks	} <u>Good</u>	Treenails	}	Windlass and Capstan	}
Waterways		Breasthooks and Stenson		Pumps	
Comings	} <u>Good</u>	Transoms, Pointers, and Crutches	}	Boats	}
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>Good where seen</u>	Keelsons	}	Sails	}
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes	} <u>Good where seen</u>	Ceiling	}	Cables	}
Topsides		Rudder		Hawsers and Warps	
Wales	} <u>seen</u>	Copper on <u>Yellow Metal</u> When put on <u>Iron</u>	}	Standing & Running Rigging	}
Plank (Bottom) and Counter		<u>Caulked</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where tested

Now done her bottom Caulked and re-hatched with yellow metal on felt - She is now fit in my opinion to continue Classed 13 A 1.

Committee's Minute 6th August 1861.

B. Weymouth

Character assigned

13 A 1 record

Certificate (if required)

Change £ 1. 1. 0

No. 23134 Survey held at London Date July 13th 18th 18 61
 on the Ship "Eveline" Master H. F. Bell
 Tonnage 899 Built at Quebec When built 1833
 By whom built G. 24 Owners Thompson &
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Nelson Dry Dock

Last Survey, No. 23134 Port of London Classed Cont 2 A 1
 SS-60-4 4.60

The present Condition of the

Decks	} <u>Good where seen</u>	Treenails	}	Windlass and Capstan	}
Waterways		Breasthooks and Stenson		Pumps	
Comings	} <u>seen</u>	Transoms, Pointers, and Crutches	}	Boats	}
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>firm</u>	Keelsons	}	Sails	}
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes	} <u>Good where seen</u>	Ceiling	}	Cables	}
Topsides		Rudder		Hawsers and Warps	
Wales	} <u>seen</u>	Copper	}	Standing & Running Rigging	}
Plank (Bottom) and Counter		<u>Good</u>		When put on <u>1839</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where tested

She is now in good and efficient condition, fit in my opinion to remain as classed

Committee's Minute 6th August 1861.

Cont 2 A 1
B. Weymouth

Character assigned

Cont 2 A 1

Certificate (if required).

Lloyd's Register Foundation

LON644-0339