

No.

Survey held at

London

Date June 25th 1861

237

on the

Ship "Isles of the South"

Master

R. Haines

Tonnage

221

Built at

Sunderland

When built

1839

By whom built

Owners

Messrs Cox & Co.

Port belonging to

London

Destined Voyage

Sydney

If Surveyed Afloat or in Dry Dock

Union Dry Dock

Last Survey, No.

22378

Port of

London.

Classed

13 A. 1.

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stenson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudders

Yellow Metal

Copper on Paper

When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done her bottom caulked, the wood ends and keel beam
 listed with yellow metal and then her bottom sheathed with yellow
 metal on paper. She is now in good and efficient condition
 fit in my opinion to remain classed 13 A. 1.

Committee's Minute

9th August 1861

Character assigned

13 A. 1

Change £ 1. 1. 02
 3.. -

Certificate (if required).

Lloyd's Register
 Foundation

LON644 - 0348