

REPORT of SURVEY for REPAIRS.

and re entry of Class A in red

No. 416 Survey held at London Date 2nd Sept 1861
on the Bⁿ Prince Albert Master

Tonnage 303 Built at London When built 1841

By whom built _____ Owners Shepherd

Port belonging to London Destined Voyage India West Indies

If Surveyed Afloat or in Dry Dock West India docks

Last Survey, No. 22732 Port London Class Unrated

REPAIRS

Classed 13 - After reat.
C 4 59

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	<u>Good</u>
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	<u>Where</u>	Keelsons	<u>Where</u>	Sails	<u>Sufficient</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	<u>Where</u>
Topsides		Rudder	<u>Seen</u>	Hawsers and Warps	
Wales		Copper		Standing & Running Rigging	<u>Seen</u>
Plank (Bottom) and Counter	<u>Seen</u>	When put on	<u>1859</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good Where seen

This Vessel is in good and efficient condition. fit for the safe conveyance of any and perishable cargoes to and from all parts of the world and eligible to be reentered A1 in red

The Amount of Fee.....£ 1 is received by me,

Special.....

Certificate (if required)

Committee's Minute 17th September 1861

Character assigned A1 in red



© 2021

Lloyd's Register Foundation

LON644-0407