

24220

# REPORT of SURVEY for REPAIRS.

Supp No. 22. *B<sup>r</sup> Montrose* Survey held at *London* Date *10 Sept 61*  
on the *B<sup>r</sup> Montrose* Master *A Baillie*  
Tonnage *364* Built at *Jersey* When built *1861*  
By whom built \_\_\_\_\_ Owners *J Scrutton*  
Port belonging to *London* Destined Voyage *Lon West Indies*  
If Surveyed Afloat or in Dry Dock *West India Docks*

Nov 24. 1861

Last Survey, No. *1054* Port *Jersey* Classed *10 A*  
REPAIRS

*The equipment of this vessel now completed by the addition of twenty fathoms of 1 3/4" chain*

## Present Condition of the

Decks	<i>Good</i>	Treenails	<i>Good</i>	Windlass and Capstan	<i>Good</i>
Waterways		Breasthooks and Stemson	<i>✓</i>	Pumps	
Comings	<i>✓</i>	Transoms, Pointers, and Crutches	<i>✓</i>	Boats	<i>Good</i>
Upper Deck Beams & Fastenings		Timbers of the Frame	<i>✓</i>	Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons	<i>✓</i>	Sails	
Planksheers	<i>✓</i>	Clamps and Shells	<i>✓</i>	Anchors No. of	<i>Sufficient</i>
Sheerstrakes		Ceiling	<i>✓</i>	Cables	
Topsides	<i>✓</i>	Rudder	<i>✓</i>	Hawsers and Warps	<i>✓</i>
Wales		Copper <i>Yln</i>	When put on <i>1861</i>	Standing & Running Rigging	<i>✓</i>
Plank (Bottom) and Counter	<i>✓</i>				

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. *Good where seen*  
*This vessel is in good and efficient condition eligible to be classed 10 A 1*

The Amount of Fee.....£ \_\_\_\_\_ is received by me, *W. Humphreys*  
Special *10 A 1* : \_\_\_\_\_

Certificate (if required) : \_\_\_\_\_  
Committee's Minute *15<sup>th</sup> October* 18 *61*  
Character assigned *10 A 1* *W*



© 2021  
Lloyd's Register  
Foundation

LON644 - 0464