

ANNUAL SURVEYS.

24249

No. 168 on the S. "Suffolk" Survey held at London Date 29th Aug to 18th Oct 1861 Master J. Martin
Tonnage 976 Built at Northam When built 1857
By whom built Owners Wigram
Port belonging to London Destined Voyage Australia
If Surveyed Afloat or in Dry Dock Wigram dry dock East Dock

Last Survey, No. 23638 Port of London. Classed 13th 12.60

The present Condition of the

Decks		Treenails		Windlass and Capstan	Good
Waterways	where	Breasthooks and Stemson	Good	Pumps	do
Comings		Transoms, Pointers, and Crutches		Boats	5 in do
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	part new
Lower Deck Beams & Fastenings		Keelsons	where	Sails	good
Planksheers	seen	Clamps and Shelves		Anchors No. of 3 B. 1 S & 2 S	
Sheerstrakes		Ceiling		Cables	complete
Topsides		Rudder	seen	Hawsers and Warps	3 in good
Wales	Good	Copper 17 in	When put on 1861	Standing & Running Rigging	do
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where tested
3 courses of Yellow Metal sheathing taken off from each bilge extending from fore chains to aft side of main chains. The seams thus exposed recaulked. Tested the caulking above bilges and found it good. Waterways recaulked. The stipped bilges resealed or felt. new Mizen Mast. Mizen Topmast mainmast 2^d and foremast she is now in good condition and eligible to continue as Classed A 1
Committee's Minute 25th October 1861
Character assigned 13th 12.60

Wm. C. Davy

Charge for Caulk £ 1.1.0 6/2/62

Certificate (if required)

No. 42 on the S. "Falcon" Survey held at London Date 18th 19th Oct 1861 Master P. Martin
Tonnage 937 Built at Greenwich When built 1859
By whom built R. Peel Owners Phillipps &
Port belonging to London Destined Voyage China
If Surveyed Afloat or in Dry Dock East India Dock Green's lower dry dock

Last Survey, No. 23577 Port of London. Classed 13th 11.60

The present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	Good	Breasthooks and Stemson	where	Pumps	in poor
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame	seen	Masts, Yards, &c.	order &
Lower Deck Beams & Fastenings		Keelsons	Good	Sails	
Planksheers	and	Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides	from	Rudder	firm	Hawsers and Warps	luffs
Wales		Copper 17 in	When put on 1860	Standing & Running Rigging	
Plank (Bottom) and Counter	where seen				

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen
Docked to sight bottom. She is where she could be seen by us in good condition and firm in her fastenings and in our opinion eligible to continue as Classed A 1

Committee's Minute 25th October 1861

Character assigned 13th 11.60

Wm. C. Davy

Certificate (if required)

LON644-0493