

ANNUAL SURVEYS.

24283

No. 53 Survey held at Deptford Date 4th Nov^r 1861
 on the "Pantaloons" Master V. Oglo
 Tonnage 234 Built at Yarmouth When built 1838
 By whom built _____ Owners J. J. Smith
 Port belonging to London Destined Voyage Sunderland
 If Surveyed Afloat or in Dry Dock See Wharf Deptford

Last Survey, No. 23546 Port of London. Classed 12c Fi
4 10.60

The present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	<u>2 No</u> <u>do</u>
Comings	} <u>where</u>	Transoms, Pointers, and Crutches	} <u>where</u>	Boats	<u>2 No</u> <u>do</u>
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	} <u>Seen</u>	Keelsons	} <u>Seen</u>	Sails	<u>do</u>
Planksheers		Clamps and Shelves		Anchors	No. of <u>13</u> <u>15</u>
Sheerstrakes	} <u>Seen</u>	Ceiling	} <u>Seen</u>	Cables	<u>Complete</u>
Topsides		Rudder		Hawsers and Warps	<u>3 No</u>
Wales	} <u>Seen</u>	Copper	} <u>None</u>	Standing & Running Rigging	<u>Good</u>
Plank (Bottom) and Counter		When put on			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Windlass linings on port side renewed. Main piece good, the appears where seen in good condition fit for the safe conveyance of dry cargoes and in my opinion eligible to remain as classed Fi 1

Committee's Minute 12th November 1861.

Character assigned Fi 1

Will C. Davy

Certificate (if required)

No. _____ Survey held at _____ Date _____ 185
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors
Sheerstrakes	Ceiling	No. of
Topsides	Rudder	Cables
Wales	Copper	Hawsers and Warps
Plank (Bottom) and Counter	When put on	Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute _____ 18

Character assigned _____



© 2019

Certificate (if required).

Lloyd's Register Foundation

LONG45-0022