

ANNUAL SURVEYS.

24418

Rev-27.1.62

No. 345 Survey held at London Date Dec^r. 21st to Jan 23rd 1862
 on the "Barque Sebastian" Master W. Begg
 Tonnage 426 Built at Sunderland When built 1833
 By whom built _____ Owners Sup^r Joyce & Co
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock Nelson Dock & London Dock.

Last Survey, No. 23590 Port of London. Classed 7 A 1.
 11, 60

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Caulked</u>	Breasthooks and Stemson	Pumps
Comings } <u>Good</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <u>Firm</u>	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides } <u>Caulked -</u>	Rudder	Hawsers and Warps
Wales	<u>Yellow Metal</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>Copper on Selt</u> When put on <u>1860</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen

Now done. Caulked from the Metal sheathing to the Centre of deck.
Six throat bolts to the Gold Beam knees on the Starboard and one on
the Starboard side renewed - the Stern bump dispensed with and her
bottom sheathing coated with Paint. She is now fit in dry

Committee's Minute 31 January 1862. Opinion to remain as classed

Character assigned 7 A 1 P. Weymouth Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute _____ 18____

Character assigned _____



© 2019

Certificate (if required).

Lloyd's Register
Foundation

LON645-0157