

24512

# REPORT of SURVEY for REPAIRS.

Change of Owners

No. 309 Survey held at London Date 25<sup>th</sup> 27<sup>th</sup> Feb<sup>ry</sup> 18 62  
on the Ship "Golden Plover" Master J. May  
Register Tonnage 359 Built at Aberdeen When built 1856  
By whom built \_\_\_\_\_ Owners Ellis & Co  
Port belonging to Aberdeen Destined Voyage Algoa Bay  
☒ Surveyed ~~Afloat~~ or in Dry Dock Gun Dock

Last Survey, No. 22903 Port London Classed GA1  
59

## REPAIRS

Put into dry dock to examine the bottom.  
Stone Ballast on board: Beams, fastenings, planks, timbers  
Masts and other parts where exposed examined, and  
as far as could be seen is in good condition

### Present Condition of the

Decks	<u>good</u>	Treenails	<u>good where seen</u>	Windlass and Capstan	<u>Dr good &amp; sufficient</u>
Waterways	<u>-</u>	Breasthooks and Stemson	<u>-</u>	Pumps	<u>2</u>
Comings	<u>-</u>	Transoms, Pointers, and Crutches	<u>-</u>	Boats	<u>4</u>
Upper Deck Beams & Fastenings	<u>-</u>	Timbers of the Frame	<u>-</u>	Masts, Yards, &c.	<u>-</u>
Lower Deck Beams & Fastenings	<u>-</u>	Keelsons	<u>-</u>	Sails	<u>Dr</u>
Planksheers	<u>good where seen</u>	Clamps and Shelves	<u>-</u>	Anchors	No. of <u>3 B.S.P.</u>
Sheerstrakes	<u>-</u>	Ceiling	<u>-</u>	Cables	<u>240 ft</u>
Topsides	<u>-</u>	Rudder	<u>-</u>	Hawsers and Warps	<u>-</u>
Wales	<u>-</u>	<u>Copper</u> <u>jet felt</u> When put on <u>1859</u>		Standing & Running Rigging	<u>-</u>
Plank (Bottom) and Counter	<u>-</u>				

### General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where examined

This vessel is in good and efficient condition  
eligible in my opinion to remain as Classed A1

The Amount of Fee.....£ 1 : : is received by me, J. W. R. Ouchman

Special..... : :

Certificate (if required) : :

Committee's Minute 11<sup>th</sup> March 18 62

Character assigned GA1



© 2019

Lloyd's Register  
Foundation

LON645-0244