

REPORT of SURVEY for REPAIRS.

No. 482 Survey held at London Date 28th March 1862
 on the S. "Runnymede" Master S. H. Rickaby
 Tonnage 720 Built at Sunderland When built 1854
 By whom built _____ Owners Brass &
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Union dry dock

Last Survey, No. 23524 Port London Classed 11 A 1
 60

REPAIRS

Recaulked from keel to metal line and the yellow metal sheathing renewed on one stake of Felt above and on paper below

Present Condition of the

Decks	<i>Good where seen</i>	Treenails	<i>Good where seen</i>	Windlass and Capstan	<i>Good and sufficient</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>Y.M.</u> When put on <u>now</u>		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested

This vessel is now in good condition and is eligible in my opinion to remain classed 11 A 1

The Amount of Fee.....£ _____ is received by me, Thos. W. Wain

Special..... 1: 1: _____

Certificate (if required) _____

Committee's Minute 15th April 1862

Character assigned 11 A 1
second of M