

ANNUAL SURVEYS.

No. Survey held at London Date Feb^r 1th 1862
on the Barque Ontario Master R. Craighead
Tonnage 433 Built at Montreal When built 1861 -
By whom built Owners Sturson & Campbell
Port belonging to London Destined Voyage Cardiff & Vera Cruz
If Surveyed Afloat or in Dry Dock "Sweetings" Dry Dock & Afloat

Last Survey, No. 469 Port of Quebec Classed

The present Condition of the

Decks <u>in good order</u>	Treenails <u>grd</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>Bowers</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3</u> <u>16.1.19</u> <u>8.1.19</u> <u>3.3.18</u> <u>1.1.21</u> <u>1.1.21</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>150 fms</u> <u>1 5/8</u> <u>60 fms of 3/4</u> <u>Hawser Chain</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>75 of 9 ins</u> <u>75 of 6 "</u>
Wales <u>"</u>	Copper <u>Linck on</u> <u>fell 18 feet high</u> <u>When put on</u> <u>Nov</u>	Standing & Running Rigging <u>in good order</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways grd.

At this date Caulked the outside from keel to Gunnel and sheathed her with Linck on felt. - This vessel is eligible for classification provided the Committee are satisfied with the weights of Anchors, and to whom the Owners have been referred Samuel Personis.

Committee's Minute 2nd September 1862

Character assigned 1st for 7 years subject to the Third Anchor 22. - Supplied See Note annexed
Certificate (if required)

No. Survey held at Date 18
on the Master
Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

The present Condition of the

Decks <u> </u>	Treenails <u> </u>	Windlass and Capstan <u> </u>
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	Pumps <u> </u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	Boats <u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame <u> </u>	Masts, Yards, &c. <u> </u>
Lower Deck Beams & Fastenings <u> </u>	Keelsons <u> </u>	Sails <u> </u>
Planksheers <u> </u>	Clamps and Shelves <u> </u>	Anchors No. of <u> </u>
Sheerstrakes <u> </u>	Ceiling <u> </u>	Cables <u> </u>
Topsides <u> </u>	Rudder <u> </u>	Hawsers and Warps <u> </u>
Wales <u> </u>	Copper <u> </u> When put on <u> </u>	Standing & Running Rigging <u> </u>
Plank (Bottom) and Counter <u> </u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute 18

Character assigned



© 2019

Lloyd's Register
Foundation
Certificate (if required).

LON646-0061