

24901

# REPORT of SURVEY for REPAIRS.

No. 284 Survey held at London Date 9<sup>th</sup> August & 5<sup>th</sup> Sept 62  
on the Ship "Mourmahall" Master Fowler  
Tonnage 846 Built at Bridport When built 1856  
By whom built \_\_\_\_\_ Owners Throuse  
Port belonging to Liverpool Destined Voyage Sydney  
If Surveyed Afloat or in Dry Dock Indalls dry dock & London Dock

Last Survey, No. 16550 Port Liverpool - Classed 13 A1  
REPAIRS 8-60

*Now done*

*Caulked from keel to gunwale and  
resheathed with yellow metal on felt*

## Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good where seen</u>	Windlass and Capstan	<u>2 D 12 Good &amp; Suff</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	<u>2</u>
Comings	"	Transoms, Pointers, and Crutches	"	Boats	<u>4</u>
Upper Deck Beams & Fastenings	"	Timbers of the Frame	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	<u>D S</u>
Planksheers	<u>Good where seen</u>	Clamps and Shelves	"	Anchors	No. of <u>3 B. S. H.</u>
Sheerstrakes	"	Ceiling	"	Cables	"
Topsides	"	Rudder	"	Hawsers and Warps	"
Wales	"	<u>Copper on felt</u> When put on <u>Now done</u>		Standing & Running Rigging	"
Plank (Bottom) and Counter	"				

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested

*This vessel is in good and efficient condition  
eligible in my opinion to remain as classed A1*

The Amount of Fee.....£ : : is received by me

Special..... 1 : 1 : 0

Certificate (if required) : 5 : -

Committee's Minute 17<sup>th</sup> September 18 62

Character assigned 13 A1

*Edward Bouchman*



© 2019

Lloyd's Register  
Foundation

LON 646-0092