

24911

REPORT of SURVEY for REPAIRS.

No. 570 on the John & Mary Survey held at London Date Sept^r 19th 1862
Tonnage 98 Built at Milford When built 1839
By whom built ✓ Owners Brennan & Co
Port belonging to Dartmouth Destined Voyage not fixed
If Surveyed Afloat or in Dry Dock in Lavender & Commercial Docks

11/23/19/62
Est

Last Survey, No. 2107 Port Milford Classed A1 in Red
SS by. & ps B.4. 4.6.

REPAIRS

Stripped yellow metal, renewed two lengths of ceiling with Foreign Oak
five stanchions of English Oak on Port bow and caulked from
keel to gunwale with decks.

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan ^{Winch}	<u>Good</u>
Waterways	<u>✓</u>	Breasthooks and Stemson	<u>✓</u>	Pumps	<u>✓</u>
Comings	<u>✓</u>	Transoms, Pointers, and Crutches	<u>✓</u>	Boats	<u>✓</u>
Upper Deck Beams & Fastenings	<u>✓</u>	Timbers of the Frame <u>where seen</u>	<u>✓</u>	Masts, Yards, &c.	<u>✓</u>
Lower Deck Beams & Fastenings	<u>✓</u>	Keelsons	<u>✓</u>	Sails	<u>✓</u>
Planksheers	<u>✓</u>	Clamps and Shelves	<u>✓</u>	Anchors No. of <u>2B, 1S, 1K</u>	<u>✓</u>
Sheerstrakes	<u>✓</u>	Ceiling <u>pt new</u>	<u>✓</u>	Cables	<u>✓</u>
Topsides	<u>✓</u>	Rudder	<u>✓</u>	Hawsers and Warps	<u>✓</u>
Wales	<u>✓</u>	Copper <u>✓</u> When put on <u>✓</u>	<u>✓</u>	Standing & Running Rigging	<u>✓</u>
Plank (Bottom) and Counter	<u>✓</u>				

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested

Is now in good and efficient condition "fit to carry dry and perishable cargoes
to and from all parts of the world" and is entitled to remain as classed.

The Amount of Fee.....£ : 1/1 : is received by me,

Special..... 1 : 1 : 0

Certificate (if required) : 2 : 6

Committee's Minute 23rd September 1862

Character assigned A1 in Red

Brennan, Lower St

Expense Ym
record repair



© 2019

Lloyd's Register
Foundation

LON 646-0101