

24938

REPORT of SURVEY for REPAIRS.

No. 38 Survey held at London Date Sept. 24th 18 62
on the Schooner "Acis" Master E. J. Medhurst
Tonnage 162 Built at Ipswich When built 1850
By whom built ✓ Owners A. Williams
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock in Princes Dock

Recd 24.9.62

Last Survey, No. 24634 Port London Classed 13 A1
4. 62.

REPAIRS

Stripped Yellow metal; renewed false keel of American plm; caulked from keel to metal line and re-sheathed with Yellow metal over felt

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame <u>where seen</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of <u>2 B, 1 S, 1 K</u>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>F & V M</u> When put on <u>1862</u>	Standing & Running Rigging
Plank (Bottom) and Counter		
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good</u>	

Is now in good and efficient condition and is in our opinion fit to remain as classed

The Amount of Fee.....£ is received by me,
Special. damage 2 : 2 : 10 6
Certificate (if required)

John Maxwell
Thos. W. Wain

Committee's Minute 14 October 18 62

Character assigned 13/1
2nd