

24972

Recd 14/10/62  
C. W. H.

# REPORT of SURVEY for REPAIRS.

No. 255 Survey held at London Date Sept<sup>r</sup> 22<sup>nd</sup> 18 62  
on the BK Pharamond Master Searle  
Tonnage 400 Built at Lardiff When built 1855  
By whom built proven Owners Jolly & Hall & Co  
Port belonging to London Destined Voyage Natal India  
If Surveyed Afloat or in Dry Dock in King and Queen dock

Last Survey, No. 22716 Port London Classed S A 1  
59.

## REPAIRS

Stripped Yellow metal sheathing, renewed on Starb<sup>d</sup> side four Top Timbers and one Stanchion of English Oak; two lengths of Sheerstrake, two of Topsides two of upper deck clamp & one of Planksheer all of Cantyze Oak, re-fitted lodging knees and four hanging knees in way of renewed work, caulked from keel to Planksheer and sheathed with Yellow metal over felt

## Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame <u>when seen</u>	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	"
Planksheers <u>pt new</u>	"	Clamps and Shelves	"	Anchors No. of <u>3 B, 1 S, 1 K</u>	"
Sheerstrakes <u>pt new</u>	"	Ceiling	"	Cables	"
Topsides <u>pt new</u>	"	Rudder	"	Hawsers and Warps	"
Wales	"	Copper <u>Y M</u> on felt When put on <u>1862</u>	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"				

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good when tested

Is now in good and efficient condition and is in our opinion fit to remain as classed.

The Amount of Fee.....£ 1 : : is received by me, John Maxwell

Special..... 2 : 2 : of

Certificate (if required) : 5 : of

Committee's Minute 21<sup>st</sup> October 18 62

Character assigned S A 1 record repair



© 2019

Lloyd's Register  
Foundation

LON 646-0162