

25100

Change of Owners.  
**REPORT of SURVEY for REPAIRS.**

No. 197 Survey held at London Date Dec<sup>r</sup> 12<sup>th</sup> 18 62  
on the Bg. "Fragévar" Master George Leadley  
Tonnage 246 Built at Grassburgh When built 1855  
By whom built 210 Kent St Owners Henry Walker  
Port belonging to London Destined Voyage Lancaster  
If Surveyed Afloat or in Dry Dock in London Dock

Last Survey, No. 2014 Port Aberdeen Classed SA1  
REPAIRS 1.62

Present Condition of the

Decks <u>Good</u>	Treenails <u>when seen</u> <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>when seen</u> <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>when seen</u> <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchor's No. of <u>SB, IS, IK</u> <u>"</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>61</u> When put on <u>61</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>when seen</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

Is now in good and efficient condition and is in my opinion fit to remain as classed

The Amount of Fee.....£

: 10 : 0 is received by me, John Maxwell

Special.....

Certificate (if required)

: 2 : 6

Committee's Minute 23<sup>rd</sup> December 18 62

Character assigned SA1



© 2019

Lloyd's Register  
Foundation

LON 646-0276



Grayson



© 2019

Lloyd's Register  
Foundation