

# REPORT of SURVEY for REPAIRS.

No. <sup>316</sup> Survey held at London Date Nov<sup>r</sup> 24<sup>th</sup> 18 62  
 on the S. Golden Pleece Master N. Wang Keys Per Owner  
 Tonnage 359 Built at Aberdeen When built 1856  
 By whom built                      Owners Ellis & G. Broom <sup>x</sup>  
 Port belonging to Aberdeen London Destined Voyage Alga Bay China  
 If Surveyed Afloat or in Dry Dock in Gun Dock <sup>x</sup> Official Return. Dec/2

Last Survey, No. 24572 Port London Classed G A1  
 2.62

## REPAIRS

Stripped Yellow metal sheathing.  
 Renewed ten bolts in staple standard knees and drove ten short butt bolts <sup>all</sup> of yellow metal; caulked from keel to gunwale and re-sheathed with yellow metal over felt.

## Present Condition of the

Decks <u>Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>where seen</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 B, 1 S, 1 K</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>F &amp; Y M</u> When put on <u>1862</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>		
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where tested Good</u>	

Is now in good and efficient condition and is in my opinion fit to remain as classed.

The Amount of Fee.....£ 7 : — : — is received by me John Maxwell

Special..... 1 : 1 : 0

Certificate (if required)                     

Committee's Minute 23<sup>rd</sup> December 18 62

Character assigned G A1



© 2019

Lloyd's Register  
Foundation

Lon 646-0279



of J. L. L.



© 2019

Lloyd's Register  
Foundation