

REPORT of SURVEY for REPAIRS.

No. 305 Survey held at London Date Jan 7th 18 63
 on the BK "Wycliffe" Master J. Ahier
 Tonnage 338 Built at Berwick When built 1851
368
 By whom built ✓ Owners Solly & Co
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock in Princes Dock

Last Survey, No. 24188 Port London Classed G.A. 1st
 Cont'd 3 qrs

REPAIRS

Stripped Yellow metal sheathing, caulked from keel to Wales and re-sheathed with Yellow metal over felt.

Present Condition of the

Decks <u>Good</u>	Treenails <u>when seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 B, 1 S, 1 K</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>F & Y M</u> When put on <u>1863</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. when tested Good

Is now in good and efficient condition and is in my opinion fit to remain as classed

The Amount of Fee.....£..... is received by me, John Maxwell

Special..... / : / : 0 MA

Certificate (if required).....

Committee's Minute 9th January 18 63

Character assigned Cont 3rd 1 record MA

Lon 646-0299



© 2019

Lloyd's Register
Foundation

Wychiffe



© 2019

Lloyd's Register
Foundation