

25155

# REPORT of SURVEY for REPAIRS.

No. 114 Survey held at London Date Jan 7<sup>th</sup> 18 63  
on the S "Invincible" Master J. Rollason  
Tonnage 657 Built at Workington When built 1857  
By whom built ✓ Owners Brushby  
Port belonging to Workington Destined Voyage           
If Surveyed Afloat or in Dry Dock in Limekiln Dock

last Survey, No. 24444 Port London Classed 13 A1  
1. 62

## REPAIRS

Stripped Yellow metal sheathing caulked from keel to gunwale and re-sheathed with Yellow metal over paper

### present Condition of the

Planks <u>Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>✓</u>	Breasthooks and Stemson <u>✓</u>	Pumps <u>✓</u>
Fastenings <u>✓</u>	Transoms, Pointers, and Crutches <u>✓</u>	Boats <u>✓</u>
Upper Deck Beams & Fastenings <u>✓</u>	Timbers of the Frame <u>where seen ✓</u>	Masts, Yards, &c. <u>✓</u>
Lower Deck Beams & Fastenings <u>✓</u>	Keelsons <u>✓ " "</u>	Sails <u>✓</u>
Winksheers <u>✓</u>	Clamps and Shelves <u>✓</u>	Anchors No. of <u>3B, 1S, 1K</u>
Strakes <u>✓</u>	Ceiling <u>✓ " "</u>	Cables <u>✓</u>
Sides <u>✓</u>	Rudder <u>✓</u>	Hawsers and Warps <u>✓</u>
Decks <u>✓</u>	Copper <u>YM</u> When put on <u>1863</u>	Standing & Running Rigging <u>✓</u>
Keel (Bottom) and Counter <u>        </u>		

### General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. where tested Good

now in good and efficient condition and is in my opinion fit to remain as classed

The Amount of Fee.....£          is received by me, John Maxwell  
Special..... 1 : 1 : 0  
Certificate (if required)         

Committee's Minute 23rd January 18 63

Character assigned 13 A1

second



© 2019

Lloyd's Register  
Foundation

LON 646-0327



Immobile



© 2019

Lloyd's Register  
Foundation