

25159

REPORT of SURVEY for REPAIRS.

11.1.62

No. 25159 Survey held at London Date Dec 20th 1862
on the Ship "Jubilee" Master A. Jones & A. Grant
Tonnage 764 Built at Workington When built 1857
By whom built _____ Owners J. Brodie
Port belonging to London Destined Voyage China
If Surveyed Afloat or in Dry Dock Brodie's Dry Dock and W. J. Dock

Last Survey, No. See annexed Report. Port _____ Classed 14 A 1.
60

REPAIRS now done. yellow-metal stripped, Caulked from
keel to gunwale, and yellow-metal renewed on felt.

Present Condition of the

Decks <u>good</u>	Treenails _____	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stenson _____	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches _____	Boats <u>good and sufficient</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>where sea</u>	Keelsons <u>where</u>	Sails <u>"</u>
Planksheers <u>"</u>	Clamps and Shelves <u>seen</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>Caulked</u>	Ceiling _____	Cables _____
Topsides <u>"</u>	Rudder _____	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>Y. M. When put on now done</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested.

This vessel is now in good condition, and in my
opinion eligible to remain as classed 14 A 1.

The Amount of Fee.....£ _____ is received by me,

Special..... 1: 1: - th

Certificate (if required) _____

Committee's Minute _____ 18

Character assigned See annexed Report
Charge for attendance £ 1. 1. -



© 2019
Lloyd's Register
Foundation
Lon 646-0331