

ANNUAL SURVEYS.

25292

Mar 16. 2. 63

No. 89 Survey held at London Date Jan to Mar 9th 1863
 on the Ship "Canadian" Master W. Guthrie
 Tonnage 703 Built at Greenock When built 1837
 By whom built Owners W. Orr
 Port belonging to Greenock Destined Voyage Hong Kong
 If Surveyed Afloat or in Dry Dock Ships' Green's Dry Dock & E. S. Dock

Last Survey, No. 17284 Port of Liverpool Classed 11A.1.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson	Pumps
Comings } <u>Good</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <u>Good</u>	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes } <u>Good where</u>	Ceiling	Cables
Topsides } <u>seen</u>	Rudder	Hawsers and Warps
Wales	<u>Yellow Metal</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>Good</u>	<u>Copper in Felt</u> When put on <u>1861</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where tested -
Now done the Windlass turned out - examined and found
good - She is in good and efficient Condition, fit in my
opinion to remain as classed 11A.1.

Committee's Minute 20th March 1863
 Character assigned 11A.1 W. W. W.

Certificate (if required)

No. 964 Survey held at London Date Feb 12th 1863
 on the Ship "Monarch" Master J. W. Gill
 Tonnage 1330 Built at London When built 1844
 By whom built Owners Ships' Green
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Ships' Green's Dry Dock

Last Survey, No. 24641 Port of London Classed Red A.1. - SS 61-84

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Partly Caulked</u>	Breasthooks and Stemson	Pumps
Comings } <u>Good</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <u>Firm</u>	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes } <u>Partly Caulked</u>	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	<u>Yellow Metal</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>Good</u>	<u>Copper in Felt</u> When put on <u>1861</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where seen
She is in good and efficient Condition, fit in my opinion for
the safe conveyance of dry and perishable cargoes to and
from all parts of the world, and to remain as classed Red A.1.

Committee's Minute 20th March 1863
 Character assigned A.1 in Red

Certificate (if required).