

25360

REPORT of SURVEY for REPAIRS.

[Signature]

No. *946* Survey held at *London* Date *9th April* 18*63*
on the Ship *"Art-Union"* Master *Morrison*
Tonnage *740* Built at *Sunderland* When built *1857*
By whom built _____ Owners *J. Shepherd & Co*
Port belonging to *London* Destined Voyage *Bombay*
If Surveyed Afloat or in Dry Dock *Repairs going in Dry Dock*

Last Survey, No. *17488* Port *Liverpool* Classed *13/4*
3-62

REPAIRS

Docked to sight bottom and patch the metal

Present Condition of the

Decks <i>Good where seen</i>	Treenails <i>Good where seen</i>	Windlass and Capstan <i>SDR Good & Sufficient</i>
Waterways <i>"</i>	Breasthooks and Stenson <i>"</i>	Pumps <i>2</i> <i>"</i>
Comings <i>"</i>	Transoms, Pointers, and Crutches <i>"</i>	Boats <i>4</i> <i>"</i>
Upper Deck Beams & Fastenings <i>"</i>	Timbers of the Frame at the openings <i>"</i>	Masts, Yards, &c. <i>"</i>
Lower Deck Beams & Fastenings <i>"</i>	Ditto Ditto at other places <i>"</i>	Sails <i>DS</i> <i>"</i>
Planksheers <i>"</i>	Keelsons <i>"</i>	Anchors No. of <i>3 B. 1 S. 2 H</i> <i>"</i>
Sheerstrakes <i>"</i>	Clamps and Shelves <i>"</i>	Cables <i>300 fms</i> <i>"</i>
Topsides <i>"</i>	Ceiling <i>"</i>	Hawsers and Warps <i>"</i>
Wales <i>"</i>	Rudder <i>"</i>	Standing & Running Rigging <i>"</i>
Plank (Bottom) and Counter <i>"</i>	<i>Plank on felt</i> When put on <i>1862</i>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. *Good where seen*

*This vessel is in good and efficient condition
eligible in my opinion to remain as classed 4/1*

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute *21st April* 18*63*

Character assigned *13A/1*

[Signature]



© 2021

Lloyd's Register
Foundation