

25368

REPORT of SURVEY for REPAIRS.

Rev'd 20/4/63
E.M.

No. 610 on the Br "Clive" Survey held at London Date March 4th to April 18th 1863
Master Penwick
Tonnage 591 Built at Newcastle When built 1854
By whom built J & W Smith Owners Smith
Port belonging to Newcastle Destined Voyage Madras
If Surveyed Afloat or in Dry Dock Messrs Youngs Dry Dock

Last Survey, No. 24490 Port London Classed 13 A 1
3-62

REPAIRS

Now done

Ship lying in shores and caulked from
Keel to Metal line and resheathed with yellow
Metal on paper Several treenails driven
out for inspection found good. The chain
cables have now been tested at the Society's
proving house No 39 also two Bower Anchors
see Certificates Nos 26 & 27

Present Condition of the

Decks	<u>Good where seen</u>	Treenails	<u>Good where seen</u>	Windlass and Capstan	<u>DM Good & Suff</u>
Waterways	"	Breasthooks and Stenson	"	Pumps	<u>2</u>
Comings	"	Transoms, Pointers, and Crutches	"	Boats	<u>4</u>
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Sails	<u>28</u>
Planksheers	"	Keelsons	"	Anchors	No. of <u>3 B. 18. 2k</u>
Sheerstrakes	"	Clamps and Shelves	"	Cables	<u>279 fms 1 1/2" Cables</u>
Topsides	"	Ceiling	"	Hawsers and Warps	"
Wales	"	Rudder	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	<u>Copper on paper</u> When put on <u>Now done</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested

This vessel is in good and efficient condition
eligible in my opinion to remain as Classed A1

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 0

Certificate (if required) : :

Committee's Minute 24th April 1863

Character assigned

13 A 1

record WM

(A.C.P.)



© 2021

Lloyd's Register
Foundation

LONG67-0074