

**REPORT of SURVEY for REPAIRS.***Change of owners*

No. 10 Survey held at London Date March 31<sup>st</sup> 1863  
 on the S. Maidon Master W. N. Nicholls  
 Tonnage 519 Built at Moulmein When built 1857  
 By whom built \_\_\_\_\_ Owners Ogilby & Moore & Co  
 Port belonging to London Destined Voyage South America  
 If Surveyed Afloat or in Dry Dock Gun dry dock

Last Survey, No. 24574 Port London Classed 13 A 1  
 61

**REPAIRS**

Now done: Top gallant forecath lower.  
 Topides recanted  
 added; Three pairs of vertical and five pairs  
 of diagonal riders in lower hold fastened with  
 Iron bolts —

This vessel was sheathed with Pine on Felt  
 fastened with metal nails in Feb 1862

**Present Condition of the**

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Opening <u>Good</u>		Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	<u>Good</u>	Do Do at other places		Sails	<u>1</u>
Planksheers		Keelsons	<u>where</u>	Anchors No. of	<u>sufficient</u>
Sheerstrakes		Clamps and Shelves	<u>seen</u>	Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder	<u>Feb 1862</u>	Standing & Running Rigging	
Plank (Bottom) and Counter		Copper <u>JM</u> When put on <u>1859</u>			
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where seen</u>				

This vessel is eligible in our opinion  
 to remain classed 13 A 1

The Amount of Fee.....£ 2: - : - is received by me,

Special..... 1: 1: -

Certificate (if required) : : -

Committee's Minute 26<sup>th</sup> June 18 63

Character assigned 13 A 1

new repair

Thos W. Mawd

Edw. R. Bouchman



© 2021

Lloyd's Register  
 Foundation