

25538

REPORT of SURVEY for REPAIRS.

No. ⁸⁴⁵ on the 137. Corporation Survey held at London Date May 25th 1863
 Master Gannon
 Tonnage 123 Built at Grimby When built 1854
 By whom built _____ Owners Foster
 Port belonging to London Destined Voyage Opica
 If Surveyed Afloat or in Dry Dock Globe dry dock

Recd. 2.7.63

Last Survey, No. 23562 Port London Classed 12 A1
60

REPAIRS

*Recaulked from metal line to water way
 seam*

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame <i>at the Openings</i> <u>Good</u>	Masts, Yards, &c. <u>Good & sufficient</u>
Lower Deck Beams & Fastenings <u>good where seen</u>	Do Do <i>at other places</i>	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves <u>where seen</u>	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Y.M.</u> When put on <u>1860</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where seen tested</u>	

*This vessel is eligible in our opinion
 to remain classed A1*

The Amount of Fee.....£ _____ is received by me, Thos. W. Wain

Special..... : :

Certificate (if required) : :

Committee's Minute 7th July 1863

Character assigned 12 A1 *W.M.*

John Maxwell



© 2021

Lloyd's Register
 Foundation
 LON647-0226