

25590

# REPORT of SURVEY for REPAIRS.

No. 291 Survey held at London Date July 2<sup>nd</sup> 18 63  
 on the S "Copenhagen" Master J. Homan  
 Tonnage 816 Built at India When built 1855  
 By whom built ✓ Owners J. H. Allan  
 Port belonging to London Destined Voyage                       
 If Surveyed Afloat or in Dry Dock in Limekiln and East India docks

Last Survey, No. 24815 Port London Classed 13 A1  
7.62

## REPAIRS

Put in two pairs of iron loading knees and six pairs of iron staple loading knees to upper deck and repaired yellow metal.

### Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>" " "</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>" " "</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>" " "</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>" " "</u>	Ditto Ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>" " "</u>	Keelsons <u>"</u>	Anchors No. of <u>3 B, 1 S, 1 K</u>
Sheerstrakes <u>" " "</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>" " "</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>" " "</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>" " "</u>	Copper <u>YM</u> When put on <u>1862</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where seen</u>	

Is now in good and efficient condition and is in my opinion fit to remain as classed

The Amount of Fee.....£ : : is received by me,

Special..... Minor

Certificate (if required) : :

Committee's Minute 31<sup>st</sup> July 18 63

Character assigned 13 A1



© 2021

Lloyd's Register  
Foundation