

# ANNUAL SURVEYS.

25036

Rec. 24/8/63  
18 63

No. 400 on the S. Shannon  
Survey held at London  
Master D. Hill  
Tonnage 732 Built at Sunderland  
When built 1853  
By whom built 825 Owners Blyths & Greene  
Port belonging to London  
Destined Voyage Mauritius  
If Surveyed Afloat or in Dry Dock in Union & West India docks

Last Survey, No. 25020 Port of London  
Classed 10 A1  
10.62

The present Condition of the  
Decks where seen Good  
Waterways " " "  
Comings " " "  
Upper Deck Beams & Fastenings " " "  
Lower Deck Beams & Fastenings " " "  
Planksheers " " "  
Sheerstrakes " " "  
Topsides " " "  
Wales " " "  
Plank (Bottom) and Counter " " "  
Treenails where seen Good  
Breasthooks and Stemson not seen  
Transoms, Pointers, and Crutches " " "  
Timbers of the Frame at the Openings " " "  
Do Do at other places " " "  
Keelsons " " "  
Clamps and Shelves where seen good  
Ceiling " " "  
Rudder " " "  
Copper F.Y.M. When put on 1861  
Windlass and Capstan Good  
Pumps " " "  
Boats " " "  
Masts, Yards, &c. " " "  
Sails " " "  
Anchors No. of 3 B, 1 S, 2 K "  
Cables " " "  
Hawsers and Warps " " "  
Standing & Running Rigging " " "  
Caulking of Bottom, Deck, and Waterways where seen Good

Is now in good and efficient condition and is in my opinion fit to remain as classed

John Maxwell

Committee's Minute 25th August 18 63  
Character assigned 10 A1

Certificate (if required)

No. 356 on the BK "Alexandrina"  
Survey held at London  
Master Dalrymple  
Tonnage 294 Built at Aberdeen  
When built 1848  
By whom built 251 Owners Falconer  
Port belonging to London  
Destined Voyage Algea Bay  
If Surveyed Afloat or in Dry Dock in Fountain and London docks

Last Survey, No. 24274 Port of London  
Classed 9 A1 in Red  
C 3 11.61

The present Condition of the  
Decks where seen Good  
Waterways " " "  
Comings " " "  
Upper Deck Beams & Fastenings " " "  
Lower Deck Beams & Fastenings " " "  
Planksheers " " "  
Sheerstrakes " " "  
Topsides " " "  
Wales " " "  
Plank (Bottom) and Counter " " "  
Treenails where seen Good  
Breasthooks and Stemson not seen  
Transoms, Pointers, and Crutches " " "  
Timbers of the Frame at the Openings where seen  
Do Do at other places " " "  
Keelsons " " "  
Clamps and Shelves " " "  
Ceiling " " "  
Rudder " " "  
Copper F.Y.M. When put on 1861  
Windlass and Capstan Good  
Pumps " " "  
Boats " " "  
Masts, Yards, &c. " " "  
Sails " " "  
Anchors No. of 3 B, 1 S, 1 K "  
Cables " " "  
Hawsers and Warps " " "  
Standing & Running Rigging " " "  
Caulking of Bottom, Deck, and Waterways where seen Good

Is now in good and efficient condition fit to carry dry and perishable cargoes to and from all parts of the world and is entitled to remain as

John Maxwell

Committee's Minute classed 25th August 18 63  
Character assigned 9 A1 in Red

Certificate (if required)