

25367

REPORT of SURVEY for REPAIRS.

No. 2536 Survey held at London Date Aug 14th 1863
on the Bk Fontebelle Master J. C. How
Tonnage 337 Built at Bristol When built 1855
By whom built _____ Owners Messrs Dawson &
Port belonging to London Destined Voyage Cape of Good Hope
If Surveyed Afloat or in Dry Dock Youngs Dry Dock

Recd 22/10/63

Last Survey, No. 25329 Port London. Classed 13 A 1
63

REPAIRS

Now done Caulked from Keel to Gunwale
and backs of Troughs Stations and the
Bottom sheathed with Yellow Metal
upon Felt

Present Condition of the

| | | | | | |
|-------------------------------|-------------------------|---|---------|----------------------------|-------------|
| Decks | } good where seen | Treenails | } good | Windlass and Capstan | } good |
| Waterways | | Breasthooks and Stemson | | Pumps | |
| Comings | | Transoms, Pointers, and Crutches | | Boats | |
| Upper Deck Beams & Fastenings | } firm | Timbers of the Frame at the openings | } where | Masts, Yards, &c. | } and |
| Lower Deck Beams & Fastenings | | Ditto Ditto at other places | | Sails | |
| Planksheers | } good where seen | Keelsons | } seen | Anchors No. of | } efficient |
| Sheerstrakes | | Clamps and Shelves | | Cables | |
| Topsides | | Ceiling | | Hawsers and Warps | |
| Wales | | Rudder | | Standing & Running Rigging | |
| Plank (Bottom) and Counter | caulked | Copper <u>Y.M. on felt</u> When put on <u>now</u> | | | |

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested

She is now in good condition and fit in
our opinion & remain as Classed
13 A 1

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : -

Certificate (if required) : :

Committee's Minute 27th October 1863

Character assigned 13 A 1 second time fit

Charge £ 1 - 1 -



© 2021

Lloyd's Register
Foundation

201649 0433