

# REPORT of SURVEY for REPAIRS.

26005

*Change of Owners*

No. in Reg. Book. **No.** 612 Survey held at London Date Dec 14 18 63  
 on the BK Elia Master Milne  
 Tonnage 351 Built at Sunderland When built 1845  
 By whom built ✓ Owners J. & A. Carter  
 Port belonging to London Destined Voyage Demarara  
 If Surveyed Afloat or in Dry Dock in W. I. Dock

Last Survey, No. 24931 Port London Classed 1/2 A in Red  
C 4 62

## REPAIRS

A stream anchor supplied.

### Present Condition of the

Decks <u>when seen Good</u>	Treenails <u>when seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>" " " "</u>	Breasthooks and Stenson <u>" " " "</u>	Pumps <u>" " " "</u>
Comings <u>" " " "</u>	Transoms, Pointers, and Crutches <u>" " " "</u>	Boats <u>" " " "</u>
Upper Deck Beams & Fastenings <u>" " " "</u>	Timbers of the Frame at the openings <u>" " " "</u>	Masts, Yards, &c. <u>" " " "</u>
Lower Deck Beams & Fastenings <u>" " " "</u>	Ditto Ditto at other places <u>" " " "</u>	Sails <u>" " " "</u>
Planksheers <u>" " " "</u>	Keelsons <u>not seen</u>	Anchors No. of <u>3 B, 1 S, 1 K</u>
Sheerstrakes <u>" " " "</u>	Clamps and Shelves <u>" " " "</u>	Cables <u>" " " "</u>
Topsides <u>" " " "</u>	Ceiling <u>" " " "</u>	Hawsers and Warps <u>" " " "</u>
Wales <u>" " " "</u>	Rudder <u>" " " "</u>	Standing & Running Rigging <u>" " " "</u>
Plank (Bottom) and Counter <u>" " " "</u>	Copper <u>F Y M</u> When put on <u>1862</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>when seen Good</u>	

Is now in good and efficient condition and is in our opinion fit to remain as classed

The Amount of Fee.....£ / : : is received by me, John Matwell  
 Special..... : :  
 Certificate (if required) : :

Committee's Minute 4<sup>th</sup> March 18 64  
 Character assigned A 1 in Red  
WMA



© 2019

Lloyd's Register  
Foundation

LON 6248 - 0124