

REPORT of SURVEY for REPAIRS.

No. in g. Book. 124 No. Survey held at London Date February 26th 1864.
 on the Ship George Crowshaw. Master Richard Alexander.
 Tonnage 570 Built at Sunderland When built 1862.
 By whom built Smurthwaite Owners Crowshaw & Co.
 Port belonging to London Destined Voyage Calcutta.
 If Surveyed Afloat or in Dry Dock "Princes" dry dock.

Survey, No. 7599 Port Sunderland. Classed 10. A. 1.
 63

PAIRS

At this date from damage received by grounding. Stripped off the whole of the Yellow Metal Sheathing Hung her in Shores. - Caulked the butts and seams of Bottom. Introduced a new False Keel, Fore-gripe or Stem piece. - Resheathed with Yellow Metal on felt, and gave her a good overhaul.

Iron whelps to "Cowleys" Windlafs have been moved bodily nearer the middle line so as to prevent the Chain Cable from fouling or jamming. -

Condition of the			
cks	<u>in good order</u>	Treenails	<u>good</u>
aterways	"	Breasthooks and Stemson	"
nings	"	Transoms, Pointers, and Crutches	"
er Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"
r Deck Beams & Fastenings	"	Ditto Ditto at other places	"
sheers	"	Keelsons	"
Sheerstrakes	"	Clamps and Shelves	"
Topsides	"	Ceiling	"
Wales	"	Rudder	<u>effick</u>
Plank (Bottom) and Counter	"	Copper	<u>Yellow Metal on felt</u> When put on <u>now</u>
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good</u>		
Windlass and Capstan	<u>in good order</u>	Pumps	"
Boats	"	Masts, Yards, &c.	"
Sails	"	Anchors No. of <u>34</u>	"
Cables	"	Hawsers and Warps	"
Standing & Running Rigging	"		"

Examined her inside and outside. She being now again in a sea worthy condition. I am of opinion she is entitled to remain as class'd 10. A. 1.

Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : -

Certificate (if required) : 5 : -

Committee's Minute 8th March 1868

Character assigned 10 A 1

Samuel Treason.



© 2019

Lloyd's Register
 LON 648 - 0134