

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 388 Survey held at London Date Jan 4 1864 1864
 on the Barque "Charlotte Ann" Master L. J. Roberts
 Tonnage 432 Built at Cowes When built 1834
438
 By whom built _____ Owners Thos. Stuart & Co
 Port belonging to London Destined Voyage Colombo
 If Surveyed Afloat or in Dry Dock London Dry Dock

Rev. 6/3/64
 C. L.

Last Survey, No. 25291 Port London Classed 1345.1.
 68

REPAIRS

How done, the yellow metal sheathing stripped off the bottom, the bottom Caulked, and re-sheathed with yellow metal on felt--

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <i>Good where seen</i>	Breasthooks and Stemson	Pumps
Comings }	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. } <i>Good and</i>
Lower Deck Beams & Fastenings } <i>Good</i>	Ditto Ditto at other places	Sails } <i>Sufficient</i>
Planksheers	Keelsons	Anchors No. of
Sheerstrakes } <i>Good where</i>	Clamps and Shelves	Cables
Topsides } <i>Seen</i>	Ceiling	Hawsers and Warps
Wales	Buddor	Standing & Running Rigging
Plank (Bottom) and Counter <i>Caulked</i>	<i>Yellow metal</i> Copper on Felt When put on <i>How</i>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. *Good where seen*

She is now in good and efficient Condition, fit in my opinion to remain as classed 1345.1.

P. T. Vaymouth

The Amount of Fee.....£ : : is received by me,

Special..... / : / : - *LL*

Certificate (if required) : :

Committee's Minute 11th March 1864

Character assigned

1345.1

record 44



© 2019

Lloyd's Register
 Foundation

LOV 648-0135